

Certificate



Certificate no.

CU 72151496 04

License Holder:

Sierra Monitor Corporation
1991 Tarob Court
Milpitas CA 95035
USA

Manufacturing Plant:

Sierra Monitor Corporation
1991 Tarob Court
Milpitas CA 95035
USA

Test report no.: USA-DOC 31080448 015

Client Reference: Tuan Ho

Tested to: UL 916:2007 R12.13
C22.2 NO. 205:2012

Certified Product: Multi-Protocol-Field-Server

License Fee - Units

Addition:

Model Designation: 9) QuickServer FS-Router-BAC1

Appendix: 1, 1-2

Licensed Test mark:



Date of Issue

(day/mo/yr)

14/10/2015